

Restoration Specific Asbestos Survey Report

Property Information:

**4045 Dolphin Circle
Colorado Springs, CO 80918**

Inspection Conducted By:

**Shannon Anderson Colorado Cert #14225
Ted Anderson Colorado Cert #14835
Asbestos Consulting Firm #ACF-15258**

Report Prepared By:

**Anderson Property Inspections
Colorado Springs, CO**

Bulk Sample Analysis Performed by:

**Reservoirs Environmental
NVLAP lab code 101896**

Table of Contents

1.0	METHODOLOGY.....	3
2.0	SCOPE OF WORK.....	5
3.0	MATERIAL CLASSIFICATION	6
4.0	CONCLUSIONS AND RECOMMENDATIONS.....	6
5.0	SKETCH.....	7
	LABORATORY RESULTS	APPENDIX A

1.0 METHODOLOGY

Anderson Property Inspections has conducted an asbestos survey for the presence of Asbestos Containing Materials (ACM) at the following address:

**Site: 4045 Dolphin Circle
Colorado Springs, CO 80918**

The Asbestos Consulting Firm and Inspectors Responsible for this project were:

Asbestos Consulting Firm #ACF-15258

Shannon Anderson Asbestos Inspector Colorado Cert #14225 Expires: 6/22/14

Theodore Anderson Asbestos Inspector Colorado Cert #14835 Expires: 4/26/14

***Copies of certifications are available upon request**

Site Visit(s): 4/10/14

Report Date: 4/16/14

Field Procedures and Analysis

-Guidelines used for the inspection were established by the Environmental Protection Agency (EPA) in order to comply with the Air Quality Control Commission Regulation No. 8, Part B "Emission Standards for Asbestos."

-Field Information was organized as per the AHERA (Asbestos Hazard Emergency Response Act) concept of Homogeneous Area. A Homogeneous Area is defined as a suspect material of similar age, appearance, function and texture. If damage is extensive enough that homogeneous areas cannot be defined, samples will be randomly obtained per functional space. Each material was grouped together as a specific Homogeneous Area or obtained from a specific functional space, sampled and then assessed for condition.

-Bulk samples of suspect ACM (Asbestos Containing Material) were analyzed by Polarized Light Microscopy (PLM) with dispersion staining, as described in 40 CFR Part 763 and the National Emissions Standard for Hazardous Air Pollutants (NESHAP). Reservoirs Environmental, Inc. was responsible for the analysis of all bulk samples. Reservoirs Environmental is an analytical laboratory accredited for the analysis of Industrial Hygiene and Environmental matrices by the National Voluntary Laboratory Accreditation Program (NVLAP), LabCode # 101896.

-Inspection & sampling will generally begin from the top down of the demo area.

-Sampling is conducted by delineating building materials into sampling designations called homogeneous areas

-A homogeneous area is defined as containing material that is uniform in visual appearance and/or confirmed as identical material based on installation date

-Homogenous areas of building materials will require only one sampling procedure

- Sampling is randomized based on the area of demolition using a simple grid system
- Once materials to be sampled are identified they are then classified as friable or non-friable
- EPA classifies materials as friable or non-friable forms of ACM. Friable materials, are defined by their ability to be crumbled or reduced to powder by hand pressure when dry and in contrast non-friable materials are not able to be reduced to powder by hand pressure. As logic dictates, friable asbestos containing materials have a much higher probability of releasing asbestos containing particulate dust into the air especially when disturbed during renovation and/or demolition activities
- The EPA breaks non-friable materials into two categories, Category I non-friable materials which are designated in good condition may remain in place during building renovation or demolition provided these materials are not rendered friable during the proposed activities, Category II non-friable materials are required to be removed prior to non-asbestos related building renovation or demolition if there is not a low probability that these materials will remain non-friable during renovation or demolition activities
- Sampling frequency is compliant with the AHERA rules for frequency and is dependent on friability and classification of the suspect material, friable surfacing materials (less than 1000sqft (3 samples) between 1000-5000sqft (5 samples) and more than 5000sqft (7-9 samples), thermal system insulations at minimum three per homogeneous area although inspector may choose to take more at their discretion and miscellaneous materials have a minimum of 1 sample required, however when over 500sqft of a miscellaneous material is present additional sampling may be employed again at the discretion of the inspector
- The inspector will clean equipment between each material sample collected to reduce the probability of any cross contamination between samples
- Bulk samples which are collected are placed in air tight containers and labeled with the appropriate set designation
- All materials sampled have been slated for demolition. Consequently invasive techniques may have been utilized to obtain or clear areas of suspect ACM.
- Material quantities are approximate as exact amount of demolition may vary depending on a number of factors i.e. success of dry-out, extent of smoke damage. Consequently, for these types of environments we recommend the contractor verify exact material amounts.
- All bulk samples will be marked for 3-5 day lab processing unless rush is requested.
- Any materials not tested but mentioned in this report are non-suspect materials (wood, metal, plastic, rubber or glass)
- A.P.I. adheres to the AHERA recommended guidelines for sampling frequency of homogeneous materials. However, we reserve the right to conduct additional sampling procedures after the initial bulk sampling lab results are received if warranted.
- Please be advised neither the EPA or Colorado Dept. of Health and Environment have established specific regulations regarding inspections related to inspecting or sampling processes in a restoration scenarios. Consequently, A.P.I. makes every effort to comply with the regulations associated with renovation type environments.

2.0 SCOPE OF WORK

Survey requested as a result of a small scale renovation project affecting the main and basement levels of this single family dwelling. Scope of work is to include replacement of the main level guest bathroom shower surround as well as wall repairs and painting of the basement bathroom. As a result three suspect material systems involved in the demolition scope provided by the onsite restoration contractor. These include a homogeneous spray textured drywall substrate wall system present in the main level and basement level bathrooms to be impacted, ceramic tile bathtub surround elements from the upper level bathroom as well as a white sealant applied around the perimeter of the ceramic tile surround in the main level bathroom to be impacted. No additional suspect materials observed which are slated for removal. This survey was characterized by a close visual inspection of all accessible affected areas. All materials sampled have been slated for demolition by the onsite restoration contractor. Selective demolition may have been conducted to access interstitial spaces suspected of containing ACM. Suspect materials have been sampled and inventoried. These suspect systems as well as non-suspect materials which are slated for removal, their corresponding locations and bulk sampling lab results can be found in the following material classification section. If during the course of demolition or due to a change in scope of affected materials additional suspect building materials not addressed in this survey are slated for disturbance it is recommended additional sampling is conducted or that the suspect building material is assumed asbestos containing and is treated accordingly.

3.0 MATERIAL CLASSIFICATION

ASBESTOS

Confirmed non-asbestos containing materials:

Sample #	Description/ Location
A4045(1-3)	White texture over white/tan drywall as homogeneous wall system present in the main level guest bathroom and basement level bathroom to be impacted
B40451	White grout and tan mastic associated with the ceramic tile tub surround in the main level guest bathroom to be impacted
C40451	White caulking applied to the perimeter of the tub and ceramic tile surround in the main level bathroom to be impacted

4.0 CONCLUSIONS AND RECOMMENDATIONS:

Only areas of non-asbestos containing building material were examined during this survey. As a result no additional precautions relating to asbestos type abatement is required for the demolition and removal of the non-detect materials systems examined in this report.


A.P.I has made every effort to survey and randomly sample all affected suspect building material associated with this loss. However, in some cases hidden or patched in materials may be present which were not readily observed. If during the course of demolition a new type of suspect material is discovered due to visual obscurity or change in project scope it is recommended additional inspection and sampling is employed or that the discovered suspect material is considered asbestos containing.

5.0 SKETCH


4/10/14 City of C. Springs

Borgja
4045 Dolphin Cir
C. Springs 80918

Bath remodel
-Kit. Cabs replaced



A4045(1-3) - Homogenous
peel textured sheet
rock walls present
as the wall material
in both upper & garden
level baths of this
single family home.



B40451 - Ceramic tile
tub surround present
in upper level
bath

C40451 - Tub/Tile surround
sealant